Traceability Data Requirements Charts

			Remark	
	Mandatory	Recommended	Veoneer	SUPPLIER
1) S/N or Lot numbers of incoming raw				
materials, components, assemblies, and for	X			
the item produced				
2) Container/box/pallet numbers of				
incoming materials, components and sub-	X			
assemblies				
3) The part/drawing/spec number and				
revision level of each incoming and	X			
produced material, component, and/or	/			
assembly				
3.5) OK/NOK result for in-process testing	X			
and measurements				
4) Actual variable data for all key process				
parameters that are critical to the item's		X	Record actual value when required	
quality and performance characteristics				
4.5) Specification limits for the parameters				
checked and recorded		X		
The state of the s			Current situation:	
			some plants / cells	Supplier code
5) Supplier number or name for each	3.7		may not record the	number may be
incoming material, component and/or sub-	X		traceability of	included in the
assembly			internal sub-	component lot
			suppliers	number.
2) 2)47 5 24 11 4 1			одружено	
6) SWI reference ; P1 (work instruction), P2	X			
(control plan), P2T (temporary SWI)				
7) Work order number, as applicable	Χ			
8) Operator ID or badge number		Х	If not a local legal issue	
O) Bradination data shift#	Х		Station visit time is	
9) Production date, shift#,	^		recommended	
10) Machine reference, robot number, tool	Х			
ID	^			
				If mandatory, to be
11) Any camera picture or digital image		X		specified at Contract
				Review
12) Outgoing shipment pallet number,				
container number, shipper number,	Χ			
processing lot number, and/or other	71			
reference numbers				
13) Maintenance operation, including	X		+ 1 clockdate in the tool to manage any event	
preventative maintenance 14) P3 Daily inspection sheet, start-				
up/change-over data sheet	X			Start-up docs
15) raw material certificates, raw material				Start-up docs
laboratory analysis,	X			
16) Prototype level traceability records	Χ			
17) Station-to-station tracking		X		
18) Station pass or fail record, and		 		
complete traceability for each scrapped	Χ		Annlicable only to	Level 1 products
product	^		Applicable of lly to	Level i products
	v			
19) Shipping document number	X			

Traceability records for the above items must or should be maintained as noted, but may be maintained outside of the facility's main traceability system.